Waste Disposal Services (WDS)

Tel: 09 530 8774



Whitford Landfill Induction and Health, Safety and Environmental rules Whilst on our site, the following requirements apply:

Health and Safety

You must be able to read and understand basic rules and verbal instructions in English, please advise if this is not possible. Communication using a Translation App is not acceptable.

我们希望您能够阅读并理解基本规则和英语口头说明才能进入我们的场所,如果无法做到这一点,请

告知。仅使用翻译应用程序进行通信是不可接受的

No smoking, vaping, drugs or alcohol

No children or animals are permitted in any vehicles; any passengers must remain in the vehicle at all times Your vehicle must have a valid COF and is in a roadworthy and legal condition

Seat belts must be worn when your wheels are moving

Mobile phones are not used whilst driving

You must not walk under suspended loads or open/raised tailgates

You are responsible for all cleaning and securing of your vehicle

You must stop at the designated area before entering tip face and wait for WDS staff directions

The handbrake must be applied when your vehicle is stationary

You must not approach plant

No littering

Any spills must be reported to site staff

You must only exit the vehicle if instructed and then stay within 1 metre of the vehicle

If your vehicle becomes stuck, you must signal to the spotter for assistance

In the event of truck recovery, you must attach the towing strops to your vehicle

You must comply with reasonable instructions from WDS staff

Photos and videos cannot be taken without prior authorisation from the site manager. Any authorised photos or videos can only be used (in any format) with the written permission of the site manager

Personal Protective Equipment (PPE) Failure to wear PPE could result in you being unable to access the site

The minimum PPE when exiting your vehicle is:

Hard Hat, hi-vis vest and non-penetrating sole, safety boots

When disposing of Asbestos Containing Material (ACM) you must wear a P2 mask

Restricted Areas The following areas are only accessible to authorised personnel

Active tip areas, flare site, leachate pond and pump sheds, irrigation fields, quarry high walls and any high wall bench access

Road Rules

Obey all road signs

The maximum speed on site is 20km/hr unless otherwise stated

If in doubt, give way to other road users

Proceed at "walking speed" over the weighbridge – no harsh braking

Drive to the conditions

Entry to the Landfill from Whitford-Maraetai Road

- Signal early, well before the turning
- Slow to approximately 10kph be prepared to stop

Waste Disposal Services (WDS)

Tel: 09 530 8774



- Ensure you have good visibility of oncoming traffic
- Do not try to beat oncoming traffic
- Be aware of traffic from Clifton Road and Trig Road
- Do not park on any side of the entry/exit road

Wheel Bath

The wheel bath must be used when there is a possibility of tracking mud out onto the main road.

- Drive through very slowly to maximise cleaning
- Only one vehicle at a time
- Beware of reversing trucks in bath

Incidents, Accidents or Damage

WDS accept no liability for truck damage occurring during tipping

If a driver believes damage or an incident has occurred whilst at the Landfill, this must be reported at the weighbridge before the driver leaves the site. A WDS manager will then be informed and investigated.

SITE ALARMS

If you become aware of any of the following: air horn; shouted warnings; vehicle driving around the site sounding the horn continuously, with headlights flashing; a vehicle with a red flashing light on the roof – make your way to the weighbridge and follow WDS staff instructions.

IF YOU SEE ANYTHING OF CONCERN, PLEASE INFORM SITE STAFF IMMEDIATELY IF IT CAN'T BE DONE SAFELY – WE DON'T DO IT

I have read, understood and agree to comply with the Whitford Landfill Site requirements:

Vehicle registration:	
Employer:	
Print name:	
Signed:	
Date:	

Waste Disposal Services (WDS)

Tel: 09 530 8774



